



34110 9th Ave. S., Suite B Federal Way, WA 98003
 (206) 529-4828 / fax (206) 774-9754

Copyright 2007-2012, Novinium, Inc. 1/27/12
 All rights reserved.

The cable should never have been bent more severely than its minimum bending radius. The minimum bending radius is 15X the cable diameter. Measure the insulation shield (semicon) or the cable jacket and multiply X 15.

Under no circumstances should a section of cable which was severely bent be straightened. The section should be cut out and discarded.

